Permit ID	Facility Name	Date of Call	Time of Call Nor	Compliance Date NonCompliance Type	Violation Description	Caller Phone #	Caller Name
WA0002062	Puget Sound Naval Shipyard	9/14/2018	4:08 PM	9/14/2018 Spill (Non-Sewage)	Spill of approx5 gallons of oil from a vessel into boomed area, there was a small sheen.	360-535-2898	Trevor Richardson
AK0053775	Denali Front Co	9/19/2018	3:46 PM	9/19/2018 Effluent Limit Violation	Exceedance of fecal weekly average limit.	(b) (6)	John Kocher
AK0053775	Denali National Park	9/12/2018	12:00 PM	9/12/2018 Effluent Limit Violation	Exceedance of chlorine. Adjustment to the process have been made and should only be a one day exceedance.		Robert
WA0025577	Naval Base Kitsap Bangor	9/13/2018	2:00 PM	9/13/2018 Effluent Limit Violation	Exceedance of temperature for the month of August due to high ambient temperatures in Hood Canal. First 3 days of August the flow recorder was not functioning properly and the data was lost.	360-396-5094	Jenny Larson
Permit ID	Facility Name	Date of Call	Time of Call Nor	ոCompliance Date NonCompliance Type	Violation Description	Caller Phone #	Caller Name
	2° - 181		······································				/ ann 22 5 X
Permit ID AKG520491	Facility Name Trident Seafood	Date of Call 9/14/2018	Time of Call Nor	nCompliance Date NonCompliance Type	Violation Description Exceedance of the .5-inch grind size.	Caller Phone #	Caller Name
	*			9/14/2018 Fish Waste	Exceedance of the .5-inch grind size.		Edward Nasive
AKG520491	Trident Seafood	9/14/2018	3:46 PM	* **	,	907-424-5390	
AKG520491 AK0037303	Trident Seafood Trident Seafood	9/14/2018 9/20/2018	3:46 PM 3:23 PM	9/14/2018 Fish Waste 9/20/2018 Spill (Non-Sewage)	Exceedance of the .5-inch grind size. Stick water spill of approx. 2 gallons into receiving water.	907-424-5390 907-698-2211	Edward Nasive
AKG520491 AK0037303 AKG520491	Trident Seafood Trident Seafood Trident Seafood	9/14/2018 9/20/2018 9/8/2018	3:46 PM 3:23 PM I:52 PM	9/14/2018 Fish Waste 9/20/2018 Spill (Non-Sewage) 9/7/2018 Fish Waste	Exceedance of the .5-inch grind size. Stick water spill of approx. 2 gallons into receiving water. Exceedance of the .5-inch grind size.	907-424-5390 907-698-2211 907-424-5390	Edward Nasive Marshall Eaton Edward Nasive
AKG520491 AK0037303 AKG520491 AKG520491	Trident Seafood Trident Seafood Trident Seafood Trident Seafood	9/14/2018 9/20/2018 9/8/2018 9/9/2018	3:46 PM 3:23 PM 1:52 PM 10:52 AM	9/14/2018 Fish Waste 9/20/2018 Spill (Non-Sewage) 9/7/2018 Fish Waste 9/9/2018 Fish Waste	Exceedance of the .5-inch grind size. Stick water spill of approx. 2 gallons into receiving water. Exceedance of the .5-inch grind size. Exceedance of the .5-inch grind size.	907-424-5390 907-698-2211 907-424-5390 907-424-5390	Edward Nasive Marshall Eaton Edward Nasive Edward Nasive Edward Nasive
AKG520491 AK0037303 AKG520491 AKG520491 AKG520491 AKG520528	Trident Seafood Trident Seafood Trident Seafood Trident Seafood Trident Seafood Alaska Glacier Seafoods	9/14/2018 9/20/2018 9/8/2018 9/9/2018 9/12/2018	3:46 PM 3:23 PM 1:52 PM 10:52 AM 11:13 PM	9/14/2018 Fish Waste 9/20/2018 Spill (Non-Sewage) 9/7/2018 Fish Waste 9/9/2018 Fish Waste 9/12/2018 Fish Waste	Exceedance of the .5-inch grind size. Stick water spill of approx. 2 gallons into receiving water. Exceedance of the .5-inch grind size. Exceedance of the .5-inch grind size. Exceedance of the .5-inch grind size. Discharge pipe has a hole in it causing discharge at 70ft instead of 100ft.	907-424-5390 907-698-2211 907-424-5390 907-424-5390 907-424-5390	Edward Nasive Marshall Eaton Edward Nasive Edward Nasive
AKG520491 AK0037303 AKG520491 AKG520491 AKG520491	Trident Seafood Trident Seafood Trident Seafood Trident Seafood Trident Seafood Alaska Glacier Seafoods Tribal	9/14/2018 9/20/2018 9/8/2018 9/9/2018 9/12/2018 9/12/2018	3:46 PM 3:23 PM 1:52 PM 10:52 AM 11:13 PM 12:56 PM	9/14/2018 Fish Waste 9/20/2018 Spill (Non-Sewage) 9/7/2018 Fish Waste 9/9/2018 Fish Waste 9/12/2018 Fish Waste	Exceedance of the .5-inch grind size. Stick water spill of approx. 2 gallons into receiving water. Exceedance of the .5-inch grind size. Exceedance of the .5-inch grind size. Exceedance of the .5-inch grind size. Discharge pipe has a hole in it causing discharge at 70ft instead of 100ft. Divers have been contacted to make repairs.	907-424-5390 907-698-2211 907-424-5390 907-424-5390 907-424-5390	Edward Nasive Marshall Eaton Edward Nasive Edward Nasive Edward Nasive Becky Fletcher

Friday, September 21, 2018 Page 1 of 1